



COLOURED SILICONE

Chemwatch: 4661-67 Version No: 6.1.1.1

Safety Data Sheet according to the Health and Safety at Work (Hazardous Substances) Regulations 2017

Chemwatch Hazard Alert Code: 1

Issue Date: 01/11/2019 Print Date: 17/12/2020 L.GHS.NZL.EN

SECTION 1 Identification of the substance / mixture and of the company / undertaking

| Product Identifier | |
|---|---|
| Product name | Cemix Tiling Sealant |
| Chemical Name | Not Applicable |
| Synonyms | Not Available |
| Chemical formula | Not Applicable |
| Other means of identification | Not Available |
| Relevant identified uses of the substance or mixture and uses advised against | |
| Relevant identified uses | Use according to manufacturer's directions. |
| Details of the supplier of the safety data sheet | |
| Registered company name | Cemix (a part of Ardex NZ) |
| Address | 19 Alfred Street Onehunga Auckland 1061 New Zealand |
| Telephone | +64 9 636 1000 |
| Fax | +64 9 636 0000 |
| Website | www.cemix.co.nz |
| Email | Not Available |
| Emergency telephone number | |
| Association / Organisation | Cemix (a part of Ardex NZ) |
| Emergency telephone numbers | 0800 ASK CEMIX |
| Other emergency telephone | Not Available |

SECTION 2 Hazards identification

Classification of the substance or mixture

Considered a Hazardous Substance according to the criteria of the New Zealand Hazardous Substances New Organisms legislation. Not regulated for transport of Dangerous Goods.

| Classification [1] | Skin Corrosion/Irritation Category 3, Serious Eye Damage Category 1 |
|---|--|
| Legend: | 1. Classified by Chemwatch; 2. Classification drawn from CCID EPA NZ; 3. Classification drawn from Regulation (EU) No 1272/2008 - Annex VI |
| Determined by Chemwatch using GHS/HSNO criteria | 6.3B, 8.3A |

Label elements

Hazard pictogram(s)



Signal word Dang

Hazard statement(s)

H316 Causes mild skin irritation.